

## Taing, Adam@Waterboards

---

**From:** Tim Parker <tparker@allencoca.com>  
**Sent:** Tuesday, January 19, 2016 11:16 AM  
**To:** Cwikla, Joshua@Waterboards  
**Subject:** RE: sump(s) at allenco

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

I mailed out our letter head responses yesterday afternoon.

All three should be there today.

Sincerely,

*Tim*

Tim Parker, Vice-President

[tparker@allencoca.com](mailto:tparker@allencoca.com)

**AllenCo**

2109 Gundry Avenue

Signal Hill, CA 90755

Phone: 562-989-6100

FAX: 562-989-6104

Cell: 310-505-8536

[www.allenco-oilwellservice.com](http://www.allenco-oilwellservice.com)

---

**From:** Cwikla, Joshua@Waterboards [<mailto:Joshua.Cwikla@Waterboards.ca.gov>]  
**Sent:** Tuesday, January 19, 2016 11:12 AM  
**To:** Tim Parker  
**Cc:** Portia Fiedler; [mpoppenheimer@allencoca.com](mailto:mpoppenheimer@allencoca.com); Tong, Weixing@Waterboards  
**Subject:** RE: sump(s) at allenco

Mr. Parker,

Please respond to the Order on company letterhead. You may email me a pdf copy of the response.

Due to the existence of the sump and its use for discharge of oil and gas related activities. Please respond accordingly with the required water well and water quality data as detailed in Sections 1-9.

Thank you,

Josh Cwikla

Joshua Cwikla, P.G.  
Engineering Geologist  
California Regional Water Quality Control Board  
Los Angeles Region  
320 W. 4th Street, Suite 200

Los Angeles, CA 90013  
Phone: (213)576-6713  
Fax: (213)576-6700  
Email: [Joshua.cwikla@waterboards.ca.gov](mailto:Joshua.cwikla@waterboards.ca.gov)



---

**From:** Tim Parker [<mailto:tparker@allencoca.com>]  
**Sent:** Monday, January 18, 2016 10:47 AM  
**To:** Cwikla, Joshua@Waterboards  
**Cc:** Portia Fiedler; [mpoppenheimer@allencoca.com](mailto:mpoppenheimer@allencoca.com)  
**Subject:** sump(s) at allenco

Dear Joshua,

At P&M Oil company there was one sump located at the Taylor well. This sump From time to time included Oil and Water. Near 28<sup>th</sup> St. Signal Hill

The sumps use was to collect tank bottom water.

However prior to January 18, 2016 the Sump has been removed and back filled.

The History of the sump is not known. It is only assumed Water and Oil were placed Into the sump.

The sump was made from Concrete bottom and 2" x 8" siding. It was 4'x4' is size.

It was used at P&M Oil co. Taylor well.

The sump was used by El Cam Oil prior to CE Allen company taking ownership in Approx. 1994

**I Tim Parker certify under penalty of the law that I have personally examined and am familiar with the information submitted in this document and all attachments and that, Based on my inquiry of those individuals immediate responsible for obtaining the information, that I believe that is true, accurate and complete. I am aware that there are significant penalties for submitting False information, including the possibility of imprisonment.**

Sincerely,

Tim

Tim Parker, Vice-President

[tparker@allencoca.com](mailto:tparker@allencoca.com)

**AllenCo**

2109 Gundry Avenue

Signal Hill, CA 90755

Phone: 562-989-6100

FAX: 562-989-6104

Cell: 310-505-8536

[www.allenco-oilwellservice.com](http://www.allenco-oilwellservice.com)